



GOVT. OF ASSAM  
TINSUKIA FIRE & EMERGENCY SERVICES STATION  
Postal Address: S.Dohuia Road, Tamulbari, PO: Tinsukia, Pin: 786125  
Contact details: Ph. No. 03742332101, e-mail id: tskfireess@gmail.com

No/TSK/F&ESS/ 103/476/25

Dated: 16/06/2025

To,

The Principal,  
Adarsha Vidyalaya Itakhuli  
Near Langkashi Outpost, Bazaloni  
Tinsukia, Assam

Sub.- Fire Audit & Inspection report of Adarsha Vidyalaya Itakhuli.

Ref.- Your application on dated 13.06.2025.

Sir,

With due honour, I would like to state that, Self Senior Station Officer of Tinsukia Fire & Emergency Service Station visited and inspected the Adarsha Vidyalaya Itakhuli, Near Langkashi Outpost, Bazaloni, Tinsukia, Assam on dated 14.06.2025 in respect of Fire Safety Measure. During my inspection I found the following Fire safety and Fire prevention measures.

1. Dated of Inspection :- 14.06.2025
2. Total Site area of the school:- 14400 SQ METER (APPROX)
3. Area for Parking:- 400 SQ FT
4. Space used for:-  
For school build up area: - 460 SQM
5. Fire Fighting Equipment:-
  - a. Fire Point :- Installed (4 nos. sand bucket)
  - b. Fire Extinguishers :- Installed
    - I. ABC Ext. 4 KG: - 06 Nos.

Reference to the above Mention safety Measures are physically checked and found satisfactory.

This is for favour of your kind information and necessary action.

Yours Faithfully

Sr. Station officer

Fire & emergency Services station  
Tamulbari.Tinsukia.Assam

**Sr. Station Officer**  
**Fire & Emergency Services Station**  
**Tamulbari, Tinsukia, Assam**

Form XI

**FORM OF APPLICATION FOR COMPLIANCE REPORT OF FIRE SAFETY REPORT  
SUGGESTIONS**

To,

The Director,  
Fire & Emergency Services, Assam  
Panbazar, Guwahati - 1

Sir,

I/We PRATITY BORPUJARI on behalf of ADARSHA VIDYALAYA ITAKHULI located at ITAKHULI TINSUKIA NEAR LANGKASHI OUTPOST BAZALONI holding District TINSUKIA do hereby inform you that Fire Prevention & Fire Safety measures have been provided in the Building/Premises as per recommendation by you vide your letter no. TSK/F&ESS/51/473/25 dated 15/06/2025 and Para wise compliance report is enclosed.

You are requested kindly to take necessary action for grant of N.O.C for the above premises/building.

Contact Details :


1. Name in Full : PRATITY BORPUJARI
2. Telephone Number :
3. Mobile Number : 7002376776

  
Principal  
Adarsha Vidyalaya Itakhuli  
Tinsukia  
Signature of the Applicant

Received by :

1. Name & Designation : *Pratity Borpujari; Principal*
2. Date & Time : *17/06/25*





GOVT OF ASSAM  
OFFICE OF THE TINSUKIA FIRE & EMERGENCY SERVICES STATION  
TINSUKIA, ASSAM, PIN-786125  
Email:- [tskfireess@gmail.com](mailto:tskfireess@gmail.com)



No/TSK/F&ESS/51473/25  
To,

Dated: 15/06/2025

THE PRINCIPAL  
ADARSHA VIDYALAYA ITAKHULI  
NEAR LANGKASHI OUTPOST, BAZALONI  
TINSUKIA, ASSAM, 786170.

SUB: - RECOMMENDATION FOR FIRE PREVENTIVE AND MEANS OF ESCAPE MEASURES IN YOUR SCHOOL BUILDING.

Sir,

With reference to the above, I have visited and inspected along with my few staff on dated 14.06.2025 and you are requested to implement the following Fire preventive and means of escape measures in your existing School (G+1) building namely ADARSHA VIDYALAYA ITAKHULI bearing Dag no.-664, Patta No.- NIL, Mouza- Tipling for safety of lives and properties as well as the building itself as per National Building code 2016.

**RECOMMENDATION OF FIRE PREVENTIVE AND MEANS OF ESCAPE MEASURES: -**


1. The setbacks as shown around the building in the proposed site plan should be kept free from any obstruction.
2. On "Fire point" consists of 3nos water buckets, 3nos sand buckets, 1no. Of ceiling hook and 1 no. Of Fire beater should be provided in front of the School/College.
3. **PASSAGEWAY AND CLEARANCES: -**
  - a) Width of main entrance of the premises shall be not less than 4.5 meters.
  - b) If an arch or covered gate is constructed, it shall have a clear head- room of not less than 5 meters.
  - c) Driveway of 5 meters must be kept for movement of fire service vehicles around the building.
4. Hose reel hose with hose reel point should be provided in each floor of the building. The length of hose reel should be such that no part of the floor remains unprotected when the hose reel is fully extended.
5. **FIRE PUMP AND PUMP HOUSE.**
  - a) At least 1 (one) no. terrace pump of 450 LPM capacity should be provided in the pump house for functioning of hose reel hose of the building. The pumps should be connected with standby power supply (D.G set) in case of failure of normal power supply.
6. Manually operated electric fire alarm should be provided in each floor of the building.
7. **INSTALLATION OF PORTABLE FIRE EXTINGUISHER:-**
  - I. CO<sub>2</sub> or DCP extinguisher of 4.5/6 kg capacity should be installed in each floor of the building. The extinguisher shall be so distributed over each floor area so that a person has to travel not more than 15 meters to reach the nearest extinguisher or in each 100 Sq. m in floor area.
  - II. Adequate No. of DCP and CO<sub>2</sub> extinguisher of 4.5/6 kg and one AFFF extinguisher of 9 Liters Capacity should be provided near the car parking area.  
Adequate No. of CO<sub>2</sub> extinguisher of 4.5 Kg capacity should be provided near the electric panel Board/ Switch gear room.  
One AFFF extinguisher of 9 Liters capacity with ISI mark should be provided near the Generator and Transformer.

**N.B.: All Fire Extinguishers should be newly introduced Indian Standard – as per IS 15683:2006**

8. The staircases/ passages should always be free from any obstruction.
9. Fire pump, External and internal lighting of the building should be connected with the standby power supply to make it functional during failure of normal power.
10. Electric wiring of the building should be either conduit or concealed type.
11. Lighting conductor should be provided to protect the building from lightning disaster.
12. To eliminate fire hazards, good housekeeping both inside and outside the building shall be strictly maintained by the staff and management in the building.
13. Separate electric circuit is to be maintained for stairway/ corridor lightning etc. in the building.  
Any alternation/ modification and change of the under-construction building will be informed immediately to the undersigned for taking necessary action.
14. Floor wise Compliance report on fire safety measures should be submitted to the undersigned for taking further necessary action.
15. Layout plan showing location of fire safety installation should be submitted to the undersigned for approval.
16. Emergency telephone number should be displayed at prominent places.
17. Employees should be trained to operate the Fire extinguishers properly as and when required.
18. The open space around the building should be kept free from any construction/ obstruction/ projection so that Fire service Heavy Vehicle can easily enter and move around the building in case of any emergency.

**PLEASE DO NOT TREAT IT AS N.O.C., FORMAL N.O.C. WILL BE ISSUED ONLY AFTER IMPLEMENTATION OF THE FIRE PREVENTIVE MEASURES AS PER SUGGESTION AND ON RECEIPT OF COMPLIANCE REPORT FROM YOUR END AND AFTER SATISFACTORY INSPECTION REPORT OF TECHNICAL OFFICERS OF THIS DEPARTMENT.**

Yours faithfully

  
Sr. Station Officer  
Fire & Emergency Services Station  
Tinsukia, Assam  
Tambulbari, Tinsukia, Assam



Office of the Principal  
**ADARSHA VIDYALAYA ITAKHULI TINSUKIA**  
P.O. Makum, Vill Bazaloni, Near Langkashi Outpost  
Dist. Tinsukia (Assam), Pin - 786170  
Estd. 2023 UDISE CODE : 18140130703  
Contact No - 8473960972 Email : adarshavidyalayalangkashi@gmail.com

Ref. No. ....

Date 24/06/25

From: Smti. Pratility Borpujari


Principal

Adarsha Vidyalaya Itakhuli

**UNDERTAKING OF FIRE SAFETY**

In favour of Chairman, CBSE, Siksha Kendra- 2 Community Centre, Preet Vihar, New Delhi- 110092.

I, Smti. Pratility Borpujari, Principal of Adarsha Vidyalaya Itakhuli, Dist. Tinsukia, Assam undertake that the Fire Safety Certificate will be uploaded as soon as it is issued by the Competent Authority as it has been applied vide application Ref . No: CAF-SAW/2025/42511 Dated 13/06/25.

  
Principal  
Adarsha Vidyalaya Itakhuli  
Tinsukia

(Smti. Pratility Borpujari)  
Principal  
Adarsha Vidyalaya Itakhuli  
Tinsukia, Assam.

